

AVIATION SERVICE DOCUMENT NOTIFICATION

TO:	Textron Aviation Inc. (Cessna) Model 560XL (Excel and XLS) modified with G5000 Owners and Operators
DATE:	September 25, 2023
SUBJECT:	5V Interior Lighting Circuit Protection Modification
CERTIFICATION AUTHORIZATION:	AML STC ST01918WI MDL Rev 24 (see Approval section for details)

COMPLIANCE

Recommended: Compliance with this STC service bulletin within the next 300 hours or 12 months.

PURPOSE

This STC Service Bulletin provides approval for a modification to the 5VDC interior lighting circuit to install circuit protection and provides approval for installer fabricated parts to support the installation before the availability of certain Garmin supplied parts.

PRODUCTS AFFECTED

Textron Aviation Inc. (Cessna) Model 560XL (Excel and XLS) modified with G5000 Integrated Flight Deck per STC ST01918WI, MDL Rev 23 or earlier.

WARRANTY INFORMATION

This modification is not warranty reimbursable.

DOCUMENTATION CONSIDERATIONS

Existing Aircraft Manual Supplements, Cockpit Reference Guides, and Pilot Guides are retained for the installation. No new documents are provided with this Service Bulletin.

The latest Aircraft Manual Supplements, Cockpit Reference Guides, and Pilot Guides are available at no cost in the Dealer Resource Center on the Garmin website <u>https://dealers.garmin.com.</u>

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.