

AVIATION SERVICE DOCUMENT NOTIFICATION

TO:	GPS 175/GNX™ 375/GNC® 355 Owner and Operators
DATE:	October 30, 2023
SUBJECT:	GPS 175/GNX™ 375/GNC® 355 Main Software Version 3.22 and GNX 375 Transponder Software Version 2.80
CERTIFICATION	

AUTHORIZATION: TSO Authorization

TSO authorization does not provide installation airworthiness approval. Separate installation airworthiness approval is required for type certified aircraft. Notification of revision to any Garmin STC(s) will be provided under a separate service bulletin.

COMPLIANCE

Recommended: Compliance with Service Bulletin 23109 is recommended at the next maintenance interval.

PURPOSE

GPS 175/GNX 375/GNC 355 Main Software Version 3.22 contains the following changes:

- Fixed an issue with daily NOTAM-TFRs that were only being shown on the first day they were issued. Now they are displayed until the FIS-B ground system stops providing them.
- Fixed an issue where the traffic output via Bluetooth interface to non-Garmin PED was interrupted when 27 or more traffic targets were present. Now traffic data is always output.

GNX 375 Transponder Software Version 2.80 fixes an issue with transponder related discrete inputs showing as not configured.

WARRANTY INFORMATION

This modification is warranty reimbursable with a deadline of May 31, 2024.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.



PRODUCTS AFFECTED

GPS 175, GNC 355, and GNX 375 products listed below with Main Software Version 3.21 and earlier are affected:

Model	Appliance P/N
GPS 175	011-04377-00
GNX 375	011-04378-00
GNC 355	011-04956-00
GNC 355A	011-04956-30

Table 1. Products Affected

DOCUMENTATION CONSIDERATIONS

The GPS 175/GNX 375/GNC 355 Pilot's Guide (Garmin P/N 190-02488-01) Rev C is applicable.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.