

# AVIATION SERVICE DOCUMENT NOTIFICATION

TO:	GTS™ 800 Traffic System Owner and Operators
DATE:	November 13, 2023
SUBJECT:	Approval of GTS 800 Main Software Version 4.13 and FPGA Version 2.10
CERTIFICATION AUTHORIZATION:	STC SA02121SE MDL Revision 5

## COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

## **PURPOSE**

This STC Service Bulletin provides notification of an update to the AML STC SA02121SE Master Drawing List revision 5 to update GTS 800 main software to version 4.13 and FPGA software to version 2.10. This software update adds support for the GI 275.

#### PRODUCTS AFFECTED

GTS 800 systems installed using GTS 8XX Part 23 AML STC SA02121SE are affected.

#### WARRANTY INFORMATION

This modification is not warranty reimbursable.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.



## **DOCUMENTATION CONSIDERATIONS**

As a result of changes related to this update, the applicable documents listed in Table 1 are required to be issued to the aircraft operator/owner before the aircraft is returned to service.

Та	bl	e	1

Document Title	Part Number	Revision (or later)
GTS 8XX Part 23 AML STC Maintenance Manual with Instructions for Continued Airworthiness	190-01279-01	2
AFMS, GTS 8XX Part 23 AML STC	190-01279-02	2

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.